



Advanced fire protection systems

Date: April 17, 2023

Nozzle Bulletin No. 174L23

Dear Valued customer,

Recently you may have noticed new packs of nozzles no longer come with strainers. Lehavot has been engaged in constant improvement of the mechanical system & parts, ensuring the best operation when the system is activated.

Today we are announcing nozzle modifications that are needed to ensure all systems function smoothly and material is ejected in the most optimal way.

Following these changes, Lehavot mandatory instructions are to remove all existing nozzle strainers for any system already installed or that's going to be installed on or before the next semiannual inspection, or installation.

Please acknowledge receipt of this bulletin by signing below. All screens must be documented as removed. We apologize for any inconvenience this may cause.

Attached is a standard repair form that will serve notice the modification have been made and that the system is in compliance with this bulletin.

Thank you for your cooperation.


Elan Alchalel
System Engineer



Advanced fire protection systems

Date: _____

Name of Company

Authorized representative

Repair form:

Date-----

Name of restaurant _____

Address:

List of Nozzles repaired:

Please send back the form to your Master Distributor for the record.